

## Drivers - Issues

| #     | Tracker | Status   | Priority | Subject  | Assignee        | Updated             |
|-------|---------|----------|----------|--|-----------------|---------------------|
| 23501 | Support | Assigned | Normal   | Install 4 more V474 cards in MC1HRM                                      | Richard Neswold | 10/31/2019 02:43 PM |
| 23153 | Support | Assigned | Normal   | Write DABBEL template for 473 devices                                    | Richard Neswold | 08/21/2019 11:18 AM |
| 22295 | Support | Feedback | Normal   | Some new Dawn VME crates have an extra field in the parameters read back | Dennis Nicklaus | 04/08/2019 09:37 AM |
| 15854 | Support | Assigned | Normal   | CAMAC front-ends need to use 720Hz clock delivery support                | Richard Neswold | 03/14/2017 09:33 AM |
| 14513 | Support | Assigned | Low      | Clean-up serial ports on camcon.fnal.gov                                 | Richard Neswold | 12/15/2016 01:37 PM |
| 12409 | Support | Assigned | High     | Extend C1151 driver to include reading                                   | Richard Neswold | 05/10/2016 10:31 AM |
| 8161  | Support | Assigned | Normal   | Upgrade the CAMAC front-ends to VxWorks 6.x and the SLE                  | Richard Neswold | 03/24/2015 10:09 AM |
| 8125  | Support | Assigned | Normal   | Upgrade the beamline front-ends to frontend.mk and MOOC 4.6              | Richard Neswold | 10/23/2018 04:42 PM |